

Release Note for Vigor2766 Series

Firmware Version:	4.4.5.8
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor2766, Vigor2766ac, Vigor2766Vac, Vigor2766ax

Vigor2766, a G.Fast router, is suitable for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2766, you can simultaneously engage these bandwidth-intensive applications, such as high-definition multimedia content, online music, movie streaming and file sharing.

New Features

- None.

Improvement

- Improved: Support for the transmission of multiple fragmented packets.
- Improved: Improve the WiFi Driver Security (CVE-2025-20631, CVE-2025-20632 and CVE-2025-20633).

Known Issue

- None.

Notes

- Vigor2766ac only supports WDS in wireless 5G.
- This version allows up to 4 LAN subnets to be configured. To avoid continuous system reboot, only the RST file can be used for firmware downgrading.

File and Modem Code

- "Vigor2766_v4.4.5.8_STD.zip" provides Annex A modem code 123230_02, 123210_30 and Annex B 123230_022, 123210_302.
- "Vigor2766_v4.4.5.8_MDM1.zip" provides Annex A modem code 126110_12, 126010_15 and Annex B 126110_122, 126010_152.
- "Vigor2766_v4.4.5.8_MDM2.zip" provides Annex A modem code 127210_04, 127110_01.
- "Vigor2766_v4.4.5.8_MDM3.zip" provides Annex J modem code 127210_04, 127110_01.

(Recommended for Germany, Austrian and Swiss users).

- "Vigor2766_v4.4.5.8_MDM4.zip" provides Annex A modem code 128210_02, 127210_04.
- "Vigor2766_v4.4.5.8_MDM5.zip" provides Annex B/J modem code 128210_02, 127210_04.
- "Vigor2766_v4.4.5.8_MDM6.zip" provides Annex A modem code 129120_05, 128210_02.
(Recommended when meeting VDSL sync issue).
- "Vigor2766_v4.4.5.8_MDM7.zip" provides Annex J modem code 129120_05, 128210_02.

VDSL2 Profile 30a is supported by modem code 129120_05(MDM6/MDM7).