

## Release Note for Vigor2830n V2

Firmware Version:	3.8.1.2
Release Type:	Normal
Applied Models:	Vigor2830n V2

Vigor2830n V2 is an ADSL2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The gigabit WAN2 and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe.

### New Features

- Add TR-069 parameters required by VigorACS 2.0.2.
- Support session-based Load Balance.

### Improvement

- Corrected: Failed to block youtube by WCF and DNS filter on chrome.
- Corrected: NAT loopback did not work when DMZ was enabled.
- Improved: Add "MS-CHAPv2 Only" option for VPN Dial-In PPP Authentication.

### File and Modem Code

Available modem codes for Annex A/Annex B are displayed as follows:

#### For Annex A Model,

- "Vigor2830n-v2\_v3.8.1.2-00\_en.zip" is used for modem code 548006\_544401 & 560816\_552011
- "Vigor2830n-v2\_v3.8.1.2-01\_en.zip" is used for modem code 567517\_562301 & 566f07\_562701
- "Vigor2830n-v2\_v3.8.1.2-02\_en.zip" is used for modem code 574307\_571801 & 573807\_571701

#### For Annex B Model,

- "Vigor2830n-v2\_v3.8.1.2-00\_en.zip" is used for modem code 548006\_544512 & 551716\_553312
- "Vigor2830n-v2\_v3.8.1.2-01\_en.zip" is used for modem code 565607\_567002 & 565606\_567002

- "Vigor2830n-v2\_v3.8.1.2-02\_en.zip" is used for modem code 573307\_571c02 & 565607\_567002

## Known Issue

- None