Release Note for Vigor2830n V2

Firmware Version:	3.8.6
Release Type:	Normal
Applied Models:	Vigor2830n V2

Vigor2830n V2 is an ADSL2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The gigabit WAN2 and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe.

New Features

Add an option to disable / enable "EAPOL Key Retries" (Wireless LAN(2.4GHz) >> Security Settings), so system administrator can configure EAPOL retries.

Improvement

• Corrected: Vigor router stopped sending Syslog into USB disk.

File and Modem Code

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

- "Vigor2830n-v2_v3.8.6-00_en.zip" is used for modem code 548006_544401 & 560816_552011
- "Vigor2830n-v2_v3.8.6-01_en.zip" is used for modem code 567517_562301 & 566f07_562701
- "Vigor2830n-v2_v3.8.6-02_en.zip" is used for modem code 574307_571801 & 573807_571701

For Annex B Model,

- "Vigor2830n-v2_v3.8.6-00_en.zip" is used for modem code 548006_544512 & 551716_553312
- Vigor2830n-v2_v3.8.6-01_en.zip" is used for modem code 565607_567002 & 565606_567002
- "Vigor2830n-v2_v3.8.6-02_en.zip" is used for modem code 573307_571c02 & 565607_567002

Known Issue

• None

RD NO: 106_11_28