

Release Note for Vigor2832 Series

Firmware Version: 3.8.3.1

Release Date: March 07, 2016

**Applied Models:
Vigor2832, Vigor2832n**

Vigor2832 series is an ADSL2/2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

- Support Vigor2832n.

File and Modem Code

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

- "Vigor2832_v3.8.3.1-00_en.zip" is used for modem code 06-06-01-07-00-01.

For Annex B Model,

- "Vigor2832_v3.8.3.1-00_en.zip" is used for modem code 06-06-00-02-01-02.

Improvement

- Improved: TCP Port 515 can be turned on or off for USB printer.
- Improved: TLSv1.0 can be turned on of off via web user interface.
- Corrected: Fixed the error of DHCP DNS allocation.
- Corrected: Fixed the error of NAT loopback issue in WAN Alias IP configuration.
- Corrected: Fixed the error of LAN flow control.

Known Issue

- None