

Release Note for Vigor2832 Series

Firmware Version:	3.8.8.2
Release Type:	Critical
Applied Models:	Vigor2832, Vigor2832n

Vigor2832 series is an ADSL2/2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

File and Modem Code

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

➤ "Vigor2832_v3.8.8.2-00_en.zip" is used for modem code 06-06-01-07-00-01.

For Annex B Model,

➤ "Vigor2832_v3.8.8.2-00_en.zip" is used for modem code 06-06-00-02-01-02.

New Features

- None.

Improvement

- This firmware includes improvements to harden the web interface against attacks. We have become aware of specific attacks against router, including DrayTek models where hackers have altered specific settings relating to your DNS servers and DHCP settings. You should urgently check those settings on your router. If they appear to have been tampered with, correct them and change your admin password and for any other config anomalies. Restore a config backup if you have one (from prior to the attack). We continue to investigate this issue but the first priority was to issue updated firmware.

Known Issue

- None