Firmware Version:	3.9.9.1
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor2832, Vigor2832n

Vigor2832 series is an ADSL2/2+ modem router with an alternative Gigabit Ethernet WAN port for load-balancing or failover. It has 4 Gigabit Ethernet LAN ports and 2 USB ports which can be used for 3G/4G WAN, temperature sensor, or NAS application. Models with built-in 802.11n Wi-Fi are available.

File and Modem Code

"Vigor2832_v3.9.9.1.zip" provides Annex A modem code 06-06-01-07-00-01, and Annex B modem code 06-06-00-02-01-02.

New Features

• None.

Improvement

- Improved: Improve the web GUI security.
- Corrected: Issues related to closing the APPE signature for network security.
- Corrected: An issue with failure to connect to Internet via SNMP server on Nagios.
- Corrected: An issue that URL Filter failure to block HTTPS websites when TLS 1.3 hybridized Kyber was enabled in the browser.

Known Issue

• None.