

Release Note for Vigor2867 Series

Firmware Version:	5.4.4
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor2867, Vigor2867be, Vigor2867be-4G, Vigor2867be-5G

The Vigor2867 Series is a multi-WAN security firewall router that integrates a DSL modem. It is compatible with various DSL protocols, including VDSL2 profile 35b Super Vectoring and ADSL2+, making it suitable for customers seeking high-speed performance.

New Features

- Support Threat Protection – Guardian, our new license-based cybersecurity solution.
- Support configuring the 2.5G port as a WAN port.
- Increase the number of More Remote Subnets entries in VPN Site-to-Site profiles from 12 to 32.
- Add a new Custom Session Timeout field to configure longer timeout values for specified protocols.

Improvements

- Corrected: An issue where IP Routed Subnet situation did not work properly.

Known Issue

- None.

File and Modem Code

- "Vigor2867_v5.4.4_STD.zip" provides modem code 5.16.19.0.

Note

- Please ensure that you use the ".rst" firmware file when recovering the router. Note that uploading the ".rst" file will reset the router to factory default settings.
For certain models, a separate ".rst" (reset) firmware file may not be provided. If the ".rst" version is not available, please manually rename the file extension of the ".all" or ".sfw" firmware file to ".rst" to create an equivalent RST firmware file.
Example:
Rename Vigorxxxx_1.2.3.4.sfw → Vigorxxxx_1.2.3.4.rst
Please ensure you back up your configuration before applying a ".rst" firmware, as all settings will be erased during the process.