Release Note for Vigor2912 Series

| Firmware Version: | 3.8.1.4 |
|-------------------|---|
| Release Type: | Critical - Upgrade recommended immediately |
| Release Date: | December 21, 2016 |
| Applied Models: | Vigor2912/Vigor2912n/Vigor2912F/Vigor2912Fn |

Vigor2912 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

None.

Improvement

• Improved: Security improvements including one or more considered critical.

Known Issue

• If TR-069 settings have been set once, the router continuously crashes after downgrading to v3.7.8 firmware.

Workaround: Add telnet command "sys tr069 clear" to clear TR-069 config in flash. Users can use this command before downgrade to avoid this problem. (But all TR-069 settings will be cleared.)