Release Note for Vigor2915 Series

Firmware Version:	4.4.6
Release Type:	Important – Review release notes and upgrade if the changes
	affect your system stability, performance, or security
Applied Models:	Vigor2915, Vigor2915ac

Vigor2915 series is a dual band router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

- Support XMPP.
- Support to show MAC address information of CPE in Syslog.

Improvement

- Improved: Improve the WebGUI Security.
- Improved: Improve the network security related to the system memory.
- Improved: Improve the WiFi Driver Security. (CVE-2025-20674, CVE-2025-20681, CVE-2025-20692).
- Corrected: An issue with a loop occurred for hotspot web portal.
- Corrected: An issue with reversed IP occurred in using DynuDDNS.
- Corrected: An issue that the router did not sync the DrayDDNS daily.
- Corrected: An issue with LAN IP Conflict after receiving ARP Probe from LAN.
- Corrected: An issue with wronly display of IP list in Dianostics>>DoS Flood Table.
- Corrected: An issue with the telnet command "vpn remote xxx on/off" not working.
- Corrected: An issue with missing the Leave info login method for hotspot web portal.
- Corrected: An issue with the HTTPS server response when accessed by a domain name.
- Corrected: An issue that failed to establish a VPN connection if the VPN server used UBDDNS.
- Corrected: An issue with abnormal server response and query timeout related to Web Content Filter.
- Corrected: An issue with TR-069 settings disappeared after rebooting the device based on the time schedule.
- Corrected: An issue with DoS Defense log not shown in Web Syslog when Firewall was selected as the Syslog Type.
- Corrected: An issue with failed to use Outlook if StartTLS was selected and SMTP port value was set to 587 for the SMTP server.

Known Issue

• None.