

Release Note for Vigor2926 Series

Firmware Version:	3.9.8
Release Type:	Normal
Applied Models:	Vigor2926, Vigor2926n, Vigor2926ac, Vigor2926L, Vigor2926Vac, Vigor2926Ln, Vigor2926Lac

Vigor2926 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Improved: Upgrading WAN2 driver to support new Ethernet PHY . Note that downgrading the firmware may disable WAN2 functionality due to incompatibility with older firmware.
- Improved: Add a new alert message “[X.X.X.X] CHAP Login Failed ()” for mail alert.
- Corrected: An issue of authorized HTTP stack-based buffer overflow.
- Corrected: An issue of self-signed certificate regeneration automatically of Vigor router before expiration.

Known Issue

- None.

Notes

- Vigor router supports the mesh network; however, it is not guaranteed to fit your environment. It might not be available and restricted due to the physical connection, actual environment, signal strength, and excessive interference.
- Use simplified APM no more.