NO: AP1101-2 V.1

Firmware Version:	1.4.3
Release Type:	Normal
Applied Models:	Vigor300B

Release Note for Vigor300B

Vigor300B, a firewall broadband router with the multi-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The multi-WAN and LAN switch facilitates unified communication applications in business CO/remote site to handle large data from the subscribed fatter pipe. The state-of-art routing feature and multi-WAN provide integrated benefits for professional users and small offices.

New Features

• None.

Improvement

- Improved: Improvement related to WebGUI security.
- Improved: Update MAC object oui database.
- Improved: Support DHCP option 121 in WAN DHCP client function.
- Corrected: Support Comma ',' in advanced DHCP options.
- Corrected: VigorACS generated an offline alarm for Vigor router when the router configured to use HTTPS for server URL.
- Corrected: Authentication over LDAP server was failed when the username contained the special character (e.g., '(').

Known Issue

• None