

Release Note for VigorAP 900

Firmware Version:	1.2.5
Release Type:	Normal
Applied Models:	VigorAP 900

VigorAP 900, the concurrent dual band wireless (2.4G/5G) access point, offers high-speed data transmission. With this high cost-efficiency VigorAP 900, computers and wireless devices which are compatible with 802.11n/802.11a can connect to existing wired Ethernet network via this VigorAP 900, at the speed of 300Mbps. Easy install procedure allows users to setup a network environment in very short time - within minutes, even inexperienced users. Also, VigorAP900 is a Power over Ethernet Powered Device which adopts the technology of PoE for offering power supply and transmitting data through the Ethernet cable.

New Features

- None.

Improvement

- Improved: VigorAP, if under Universal Repeater mode, can be managed by Vigor router (central management, AP).
- Improved: Support an option to enable/disable the telnet access for VigorAP.
- Corrected: USB Thermometer was not detected in some configurations.
- Improved: Web page modification to meet the GDPR.
- Corrected: Unable to receive UDP connection packets from VigorAP connected to the CPE through NAT.
- Corrected: Unable to search nearby VigorAP and display on VigorACS due to the problem of content length.
- Corrected: Unable to configure LAN gateway, sometimes.
- Corrected: Channel 36~48 were checked as filtered out channels on Wireless LAN (5GHz)>>Advanced Setting. However, the Active Channel was still displayed as “36” on Wireless LAN>>General Setup.
- Corrected: Unable to display the vendor of Apple product on Mobile Device Management>>Detection.
- Corrected: Product registration page could not work if accessing web user interface through HTTPS.

Known Issue

- None

Notes

- None