Release Note for VigorAP 910C

Firmware Version:	1.2.3
Release Type:	Normal
Applied Models:	VigorAP 910C

VigorAP 910C is a ceiling mount Access Point with PoE for offering power supply and support 300Mbps @2.4GHz, and 866Mbps @5GHz (11ac).

New Features

• Add TR-069 parameters required by VigorACS 2.1.0.

Improvement

- Improved: Add more features (e.g. compression) and parameters (e.g. channel width) for AP management.
- Improved: Add "Inform Test Button", "Last Inform Response Time" and "URL Wizard".
- Corrected: Potential memory leakage issue.
- Corrected: Several WUI issues (e.g. AP Discovery, data flow monitor) for wireless LAN.
- Corrected: Each 5GHz channel above 48 was shown as channel 36 if you enabled a 2nd SSID for wireless LAN (country code: DE).
- Corrected: When 2.4G and 5G SSIDs had the same name, 2.4G clients and 5G clients could not reach each other.

Known Issue

None.

Notes

• To enhance the security among wireless clients, the SSIDs on the different bands (2.4GHz / 5GHz) will be isolated. That is, wireless clients with different bands can not communicate with each others even they are on the same subnet.

RD NO: 106_09_06