

Release Note for VigorAP 920R Series

Firmware Version:	1.4.5
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	VigorAP 920R, VigorAP 920RP, VigorAP 920RPD

VigorAP 920R outdoor access point is designed to meet the requirement of wireless network connection in rugged and hazardous locations. It is suitable for harsh physical environments including wind, rain and snow; and simultaneously it offers various functions to establish seamless, reliable, secure Wi-Fi network with high performance.

New Features

- Add the new feature of event alert (Diagnostics>>Alert Event).

Improvement

- None.

Known Issue

- Web access via HTTPS doesn't work well after the firmware upgrade. It is recommended to use HTTP instead or use either of the methods below to fix this problem temporarily.
 - (a) Enable "Enforce HTTPS Access" on web System Maintenance >> Management.
 - (b) Use "https://{IP}/login.asp" to access web. (Add "/login.asp" manually after IP. For example: "https://192.168.1.11/login.asp")