### **Release Note for VigorBX 2000 Series**

### Firmware Version: 3.8.1.1 Release Date: November 20, 2015 Applied Models: VigorBX 2000

VigorBX 2000 series delivers a new architecture for flexible extension-logic communications by using the Session Initiation Protocol (SIP) to establish voice connections between users and combines the rich-features of the PBX with networking advantages combined with trunk and scalability.

#### **New Features**

• None.

#### Improvement

- Improved: Add web page for **Diagnostic>>ARP Cache Table** of Non-Vodafone to classify LAN/WAN ARP entries.
- Improved: Add new TR-069 parameters. InternetGatewayDevice.X\_00507F\_VoIP.SIP.NATTraversal.SIPALGEnable InternetGatewayDevice.X\_00507F\_VoIP.SIP.NATTraversal.SIPALGPort
- Improved: Bind WAN interface for SSL VPN service.
- Corrected: X.509 Certificate could not be imported for the length was not matched. In this version, maximum length was modified up to 4K.
- Corrected: DMZ subnet broadcast packet sent to LAN1.
- Corrected: Wrong routing table was added for SSL VPN (LAN to LAN).
- Corrected: Error blockaded Google website via APP Enforcement Profile.
- Corrected: RaidCall 8.1.8 could not be blocked via APP Enforcement Profile..
- Improved: Some wrong information in telnet command.
- Improved: Modify the web page for CVM, VPN Wizard.
- Improved: Settings of SIP Alias List, Call Barring White List Number, Digit Map and Voice Mail SMT can be converted from VigorIPPBX into VigorBX2000 precisely via System Maintenance >> Configuration Backup.
- Improved: Support new modem code: 576d17\_572801.

# **Known Issue**

• None.

# Notes

• None.