# **Release Note for Wireless APP (iOS)**

Firmware Version:	1.3.0
Release Type:	Normal
Applied Models:	See below

DrayTek Wireless APP is an ideal mobile application for on-premises Vigor router / AP configuration and monitoring. It allows you to easily configure and manage the Mesh Wireless network with the following key benefits:

- Intuitively and easily set up a Vigor Mesh group from scratch
- Scan and sync configurations automatically to newly added VigorAPs
- Basic configuration for WiFi name / password, channel, admin password, TR-069 and etc
- Monitor the Mesh node (APs) for WiFi signal strength and topology
- Monitor WiFi clients with device names, signal strength, real-time data rates and etc

### **New Features**

- Support the Alert Event function (only for VigorAP 903).
  - Allow viewing Alert Event in dark mode.
  - Add the Alert Event Count of Device Status page.
  - Display Alert Event Chart and List on the Device page.
  - Display the Alert Event count for mesh root/AP mode on the Dashboard page.
- Support the function of sending the Syslog Report mail.
- Support Syslog Access Setup by clicking Diagnostics on the Device page.
- Add a new page of Network Diagnostic.
  - Add Network Status Score Result.
  - Add Ping Test for single/multiple devices with Line Chart/Text view.

#### Improvement

• None.

#### **Known Issue**

• None.

# **Applied Model**

- VigorAP 802 (with firmware 1.4.1 and above)
- VigorAP 903 (with firmware 1.4.1 and above)
- VigorAP 906 (with firmware 1.4.6 and above)
- VigorAP 912C (with firmware 1.4.1 and above)
- VigorAP 918R (with firmware 1.4.0 and above)
- VigorAP 920R (with firmware 1.4.0 and above)
- VigorAP 960C (with firmware 1.4.0 and above)
- VigorAP 1000C (with firmware 1.4.0 and above)
- VigorAP 1060C (with firmware 1.4.0 and above)
- Vigor2765 Series (with firmware 4.3.1 and above)
- Vigor2862ac/Vac/Lac (with firmware 3.9.5 and above)
- Vigor2865 Series (with firmware 4.2.2 and above)
- Vigor2926ac/Vac/Lac (with firmware 3.9.5 and above)
- Vigor2927 Series (with firmware 4.2.4 and above)

## Note

• Support the Alert Event function for VigorAP 903 (with firmware 1.4.7 and above) only.